OUNTRY.	EAST CATTIES IN		25X1
)PIC	Parchim Airfield	- Marie to realize the parameter of the last to the first the state of	Z3 / I
		nyky (1947) aukkiji (ilonia mant schramincher Chilosophia (1940) (ilonia un not not un naturalis (1960) (ilonia	25X1
/ALUATIO	NPIACE OBTAINED	THE PROPERTY OF THE TAX AND ADDRESS AND AD	25 X 1
	CONTENT		25X1
	AINEDOATE PREPARED	16 April 1953	
			<u> </u>
	2		en e
AGES	2 ENCLOSURES (NO. & TYPE)	•	nera en egenetarionen in allate architetto in s
EMARKS.			- echanistr Algorithm (Antholis Printed Co.)
his is Ul	NEVALUATED Information		
			u (page v elektrist) stala visitate sa
			25 X 1
	On 6 March 1953, the runway a probably owing to heavy frost, was in poor condit particularly near the joints, and the concrete su which was three centimeters thick, appeared to be	ion. Holes had formed, rface of the runway, ruffled and heavily	25X1
2.	probably owing to heavy frost, was in poor conditi- particularly near the joints, and the concrete sur- which was three centimeters thick, appeared to be damaged in parts. Through its entire length, there On both sides of the runway, there was a concrete 40 cm wide and covered by concrete slabs. The draf- be neglected, because the ditches were half filled the runway and taxiway wide respectively. The airfield barracks were inte windows were broken and the furniture was missing Near the spur track of the installation half dug into the earth. Each of the containers he	ion. Holes had formed, rface of the runway, ruffled and heavily were several cracks. d drainage ditch 30 to lage system appeared to d with water. were 80 and 12 meters act but neglected; the	25X1
2.	probably owing to heavy frost, was in poor condition particularly near the joints, and the concrete surwhich was three centimeters thick, appeared to be damaged in parts. Through its entire length, there on both sides of the runway, there was a concrete 40 cm wide and covered by concrete slabs. The drain be neglected, because the ditches were half filled the runway and taxiway wide respectively. The airfield barracks were into windows were broken and the furniture was missing. Near the spur track of the installation	ion. Holes had formed, rface of the runway, ruffled and heavily were several cracks. I drainage ditch 30 to lage system appeared to were 80 and 12 meters act but neglected; the eight fuel containers ad an estimated capacity spur track, which origi-	25X′
	probably owing to heavy frost, was in poor conditi- particularly near the joints, and the concrete sur- which was three centimeters thick, appeared to be damaged in parts. Through its entire length, there On both sides of the runway, there was a concrete 40 cm wide and covered by concrete slabs. The drai- be neglected, because the ditches were half filled the runway and taxiway wide respectively. The airfield barracks were inte windows were broken and the furniture was missing Near the spur track of the installation half dug into the earth. Each of the containers he of 24 cubic meters. It was planned to extend the	lon. Holes had formed, rface of the runway, ruffled and heavily were several cracks. I drainage ditch 30 to lnage system appeared to it with water. Were 80 and 12 meters act but neglected; the dight fuel containers ad an estimated capacity spur track, which originers. The reconditioning a to quarter workers of materials. Improventatin Smyrna (phonetic tion twice a week. The secial project. Negotians Soviet construction was allocated by the lin. The sum budgeted 1.5 million eastmarks	25X′

SECRET/CONTROL - U.S. OFFICIALS ONLY

-2-

25X1

was not planned. However, it was to be provided with a new surface 15 cm thick and 70 meters wide. This surface is to be laid on top of the existing surface. Five-meter asphalt strips on both sides are to establish a smooth connection between the two surfaces. The new runway surface was to be built with 330 kg of cement per cubic meter, a compressive strength of Wb 28 per 250 kg, and a bending and tensile strength of 43 kg per square cm. The compressive strength was the same as that of the runway at Brani airfield, which otherwise had a bending and tensile strength of only 38 kg. The German experts suggested that the new surface be laid on a two-cm layer of fine sand covered by oil paper. However, the Soviet construction headquarters in Werder planned to lay it immediately on the cracked old surface. A sum of 2.2 million eastmarks was allocated for the construction of the new runway. The taxiway was to be reconditioned in 1954.

- 5. It was planned to construct 40 shrapnel-proof aircraft revetments southeast of the runway and near the former hangars.
- 6. In mid-March construction plans for the improvement of the airfield were being examined in Werder. The chief German construction supervisor was one Mueller, who was assisted by Moritz Buchheester, formerly construction supervisor at Brand airfield. Aggregate materials and cement were to be hauled to the concrete mixing machines by rail with the help of diesel engines, while the finished concrete was to be hauled to the construction sites by special trucks having a load capacity of 2.5 cubic meters. These trucks were to be delivered by Hungary. In mid-March, the construction site was being prepared at the airfield. Construction work proper had not yet been started. A mine-locating detail was looking for hidden teller mines, because such mines had been found at the field. Concreting work was expected not to be started before mid-April. 1
- Comment. The report, which is believed to be correct, supplements previous information. The curtailment of construction work at the field in favor of the improvement of Jueterbog airfield was reported previously. Captain Smyrna was reported for the first time; he may be identical with a Captain Smirnov attached to the Soviet construction headquarters in Werder. Smirnov was observed at various airfields.

25X1

SECRET/CONTROL - U.S. OFFICIALS ONLY